General Disclaimer

One or more of the Following Statements may affect this Document

- This document has been reproduced from the best copy furnished by the organizational source. It is being released in the interest of making available as much information as possible.
- This document may contain data, which exceeds the sheet parameters. It was furnished in this condition by the organizational source and is the best copy available.
- This document may contain tone-on-tone or color graphs, charts and/or pictures, which have been reproduced in black and white.
- This document is paginated as submitted by the original source.
- Portions of this document are not fully legible due to the historical nature of some
 of the material. However, it is the best reproduction available from the original
 submission.

Produced by the NASA Center for Aerospace Information (CASI)

in the interest of early and wide dissemination of Earth Resources Survey Program information and without liability for any use made thereot.*

HOKKAIDO NATIONAL AGRICULTURAL
EXPERIMENT STATION
HITSUJIGAOKA, SAPPORO, JAPAN

ACQ. ER.

F MAR 0.5 1975 Gel

DOG 4 0 0 3

RECFIVED
NASA OT ACCULTY

Title of Investigation: 28990 Investigation of Environmental

Change Pattern in JAPAN

E7.6 10.17.2 CR-146372

Principal Investigator: Takakazu MARUYASU

Science University of Tokyo

Noda City, Chiba ken , 278, JAPAN

Quarterly Progress Report for Period

October 1975-January 1976

Original photography may be purchased from: EROS Data Center 10th and Dakota Avenue Sioux Falls, SD 57198

Name and adress of

National Sponcering

Science and Technology Agency

Agency

Kasumigaseki 2-2-1 Chiyoda ku,

Tokyo, 100, JAPAN

(E76-10172) INVESTIGATION OF ENVIRONMENTAL CHANGE PATTERN IN JAPAN: INVESTIGATION OF SOIL EROSION IN HOKKAIDO WHICH IS CAUSED BY

N76-18593

Subject THAWING OF SOIL WATER IN LATE SPRING

Unclas

Quarterly Progress Report. (Science Univ. of G3/43 00172 1. Investigation of Soil Erosion in Hokkaido which is caused by

Thawing of Soil Water in Late Spring

Co-Investigator: Shigechika HAYASHI

Upland Farming Division,

National Agricultural Experiment

Station.

Memuro, Hokkaido, 082, JAPAN

HOKKAIDO NATIONAL AGRICULTURAL EXPERIMENT STATION HITSUJIGAOKA, SAPPORO, JAPAN

We have received two kinds of scene, Obihiro and Monbetsu, on June 11, 1975. It is impossible from those imageries to examine the soil erosion caused by thawing of soil water. However, we are trying to study on following problems.

LANDSAT imageries were compared with conventional soil maps, because identification of soil types from the imageries is necessary to develop this investigation. Conventional soil maps are made on the basis of soil profile observation, on the other hand LANDSAT can detect only the surface of soils. Therefore, it was found that they did not always agree well. (See the figure.)

According to the imageries from MS^C on Aug. 22, 1975, excess-moisture injury of crops were recognized along the run-off pattern of rain water. As it seems to be reasonable to assume that the run-off pattern of rain water is similar to that of soil erosion by thawing water, we shall interprete LANDSAT imageries about the areas of damaged crops.

HOKKAIDO NATIONAL AGRICULTURAL EXPERIMENT STATION HITSUJIGAOKA, SAPPORO, JAPAN




Fig. The case showing different response of reflection within the same soil type.

(A: Alluvial Soil, B: Andosol-Brown. Using 5-band.)

ORIGINAL PAGE IS OF POOR QUALITY